
## **GEOMETRIC PARAMETERS**





Transverse

Transverse

roughing with

cuts along an


Radius recovery with longitudinal cuts to remove residual material


roughing with


cuts along the

finished profile









If the inclined profile starts after a straight line, the macro automatically recognises the type of profile by entering the X parameter for the Z coordinate of the start of the inclined line.

G65P8029Z0W-15D160U65E-28 X-21 A60B0V.4R4I1M5Q3S2F0.5K0.4C0.5H0T1



Roughing transverse cuts are carried out close to the profile, leaving the desired allowance for finishing set by parameter V.


D200E150X175**M8**Z-30W-130A0B0I1.5...

S=1 ROUGHING

S=2 ROUGHING+FINISHING

S=3 FINISHING

CASE2: Only for finished profile with 0° sides



D200E150X175**M8Y10**Z-30W-130A15B15I1.5...

S=1 ROUGHING

S=3 FINISHING

S=4 RADIUS RECOVERY

S=5 ROUGH.+RADIUS RECOVERY

S=6 ROUGH.+RADIUS RECOVERY+FINISHING

## PARAMETER LIST

D=MAX. DIAMETER SIDE 2 U=MIN. DIAMETER SIDE 1

Z=Z-COORDINATE OF GROOVE START ON THE X SIDE MIN.

W=Z-COORDINATE OF GROOVE STAR ON THE X SIDE MAX. (OMIT IF SAME AS Z)

E=Z-COORDINATE OF GROOVE BOTTOM

A=ANGLE X SIDE MAX.

B=ANGLE X SIDE MIN.

M=RADIUS SIZE OF THE GROOVE BOTTOM

V=SIDE ALLOWANCE

R=INSERT RADIUS

Q=RADIAL SAFETY DISTANCE

I =DEPTH OF CUT

T = 0 or null S/R T=1 ONLY START IN X-

S 1=ROUGH. 2=ROUGH.+FINISHING 3=FINISHING

4=RADIUS RECOVERY 5=ROUGH.+RADIUS RECOVERY 6=ROUGH.+RADIUS RECOVERY+FINISHING

C=RADIUS/CHAMFER SIDE 1

H=RADIUS/CHAMFER SIDE 2

X=Z-DIMENSION OF ANGULAR START

Y= BOTTOM RADIUS OF THE RADIUS RECOVERY

J=VALUE FOR CHIP BREAKAGE NULL OR ZERO WITHOUT BREAKAGE

F=STARTING FEEDRATE

K=FINISHING FEEDRATE

THE ROUGHING FEEDRATE IS TAKEN FROM THE PROGRAM

